FINAL RANDOM INSPECTION REPORT

M-Grand Inspection Agency · Quality You Can Trust — Worldwide

MG-SAMPLE-0001
Sample report

Order summary

Client	Contoso Apparel Ltd
Supplier	Fabrikam Garments EPZ Ltd
Inspection site	Athi River EPZ, Machakos, Kenya
Inspection date	4 November 2026
Inspector	Jeckonia Omotto
Product	Men's crew-neck T-shirt, 100% cotton jersey
Style / PO	ST-0001 / PO-0001
Order quantity	4,200 pcs, 3 colours, sizes S–XL
Inspection type	Final random inspection (FRI)
Status at visit	100% produced, 100% packed
Standard	ISO 2859-1, single sampling, normal inspection, general level II

Overall result

ACCEPTED

Lot size	**4,200 pcs**
Code letter / sample	**L / 200 pcs**
AQL crit. / major / minor	**0 / 2.5 / 4.0**
Critical found (accept 0)	**0**
Major found (accept 10)	**3**
Minor found (accept 14)	**6**

SAMPLE REPORT

Checklist results

Check	Criteria	Result	Remarks
Quantity and packing	PO quantity, assortment, carton count	**Conform**	4,200 pcs in 70 cartons, assortment as PO
Workmanship	AQL 2.5 / 4.0 against approved sample	**Within AQL**	3 major, 6 minor; see defect list
Measurements	Spec sheet, size M, 5 pcs per size	**Noted**	Chest width +1.5 cm on 1 of 20 pcs measured
Labels and marking	Main, size and care labels; carton marks	**Conform**	—
Fabric and print	Shade against approved swatch, hand feel	**Conform**	No shade variation between cartons
Needle and sharp-tool control	Process review on the packing line	**Conform**	Broken-needle log complete
Smell and odour screening	Unusual chemical or musty odour	**Conform**	Screening only; not a laboratory test

Defect list

#	Description	Location	Class	Qty
1	Open seam, 1.5 cm	Left side seam	Major	2
2	Skipped stitches	Bottom hem	Major	1
3	Untrimmed thread end over 1 cm	Neck rib	Minor	4
4	Light soiling, removable	Back body	Minor	2

Measurements, size M (cm)

Point of measure	Spec	Tol ±	Pc 1	Pc 2	Pc 3	Pc 4	Pc 5
Chest width (½)	52.0	1.0	52.0	51.5	**53.5**	52.5	52.0
Body length (HPS)	72.0	1.5	72.5	71.5	72.0	73.0	72.0
Sleeve length	20.5	1.0	20.5	21.0	20.0	20.5	20.5
Neck width	18.0	0.5	18.0	18.0	18.5	17.5	18.0

Photo evidence



#1 Open seam, left side seam



#2 Skipped stitches, hem



#3 Thread end, neck rib



Carton marking, as PO

Scope and limitations

A routine inspection records what was checked, the criteria used, the sample reviewed and the findings. It is not a laboratory test, a statutory approval, a product certification or a guarantee of future performance. Where specialist testing or official certification is needed, we refer it to a suitably qualified laboratory or the authorised body. Findings apply only to the sample inspected on the day.

Jeckonia Omotto
Inspector, 4 November 2026

Georgeinah Kalondu
Director of Quality, technical review before issue